

EAST DELHI MUNICIPAL CORPORATION
OFFICE OF THE EXECUTIVE ENGINEER-[M SHAH (N)]-II
C-12, YAMUNA VIHAR DELHI-110053

No. E.E.-[M Shah(N)]-II/A.E./2020-21/...95

Dated 04/1/2021

To

The Manager

BHAGIRTHI BAL SHIKSHA SADAN SECONDARY SCHOOL

D-7/53, D-Block Gali No. 7, Dayalpur Extn.

Delhi-110094

SUBJECT:- SCHOOL BUILDING FITNESS CERTIFICATE.

In reference to your letter No. BBSSSS/MANAGER/121 dated 31.12.2020 on the above cited subject, this is to certify that BHAGIRTHI BAL SHIKSHA SADAN SECONDARY SCHOOL, D-7/53, D-Block Gali No. 7, Dayalpur Extn, Delhi-110094 has been inspected by the concerned Junior Engineer from safety point of view of building and found satisfactory condition at present.

This certificate has no bearing on unauthorized construction in the premises. If any and no any dispute regarding title of land.

This certificate is valid for one year

Ishana

Principal
Bhagirathi Bal Shiksha Sadan Sec. School
Recognised & Affiliated to C.B.S.E.
D-Block, Gati No. 7, Dayalpur Exta.
Debi-110094

Manager Bhagirathi Bal Shiksha Sadan Sec. School

Recognised & Affiliated to C.B.S.E D-Block, Gali No 7 Dayalpur Extra Delhi-110094 ASSTT. ENGINEER M-II SHAH(NORTH)

Asstt. Engineer (M)-II SH-N Municipal Corporation of Delhi C-12, Yamuna Vihar, Deihi-53