



SUSHMA & ASSOCIATES

Govt. Approved Structural Engineer and
Rain water Harvesting work etc.



Lic. No. SE/6131

Date 02/07/2025

STRUCTURAL STABILITY CERTIFICATE

Certified that I have personally inspected the School building known as
"BHAGIRATHI BAL SHIKSHA SADAN" Situated at D-7/53,
DAYALPUR, DELHI-110094. The Building is designed on the basis of
calculations and satisfies the safety requirements. As per visual inspection of the
building, it is further certified that the structure of the building is safe and sound
for school purpose.

Note: This Certificate is valid for One Year from the Date of Issuance.


Er. Sushma

Er. SUSHMA
STRUCTURAL ENGINEER
M.C.D. Licence No. SE/6131
Off :- Plot No. 490, Vill. Baprola Near Primary
School, Najafgarh Nangloi Road, Delhi-110043
Mob. 9729024979, 9466708110

Office Add:- House No. 490 Village -Baprola Near Primary School,
Najafgarh Nangloi Road, Delhi-110043

Email - sushma291093@gmail.com | Ph - 9729024979, 9466708110


Manager

Bhagirathi Bal Shiksha Sadan Sec. Sch
Recognised & Affiliated to C.B.S.E
D-Block, Coli No 7 Dayalpur Extn
Delhi-110094



Principal
Bhagirathi Bal Shiksha Sadan Sec. School
Recognised & Affiliated to C.B.S.E
D-Block, Coli No 7 Dayalpur Extn
Delhi-110094

Scanned with OKEN Scanner